EMERY MINE



Consolidation Coal Company Request For Facsimile Transmission

Date From Ext. Employee To Phone No. Name Room No. Department Location (City) No. of Originals Special Instructions

EMERY-MINE FAX 801-286-2338

OFFICE 801-286-2301

DUCOM 286-2301, 2475, 2476

WAREHOUSE 802-286-2211



CONSOLENERGY...

Emery Mine P.O. Box 527 Emery, Utah 84522

June 4, 2002

Priscilla Burton, Soils Reclamation Specialist Mine Land Reclamation Program 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

RE: Excavation Sequence for Topsoil Recovery For 4th East Portal Excavation; Consolidation Coal Company, Emery Mine

As per our conversation on June 4,2002, please find enclosed a sequence for stripping and stockpiling topsoil and a refined map of soil units at the Emery Mine's 4th East Portal Site. Topsoil recovery and drainage structure sequence will be as recommended by yourself and Mr. Darby in the meeting. The soils map was refined by Patrick Collins and Jim Nyenhuis of Mt. Nebo Scientific during a topsoil survey on May 31,2002.

Topsoil Recovery and Drainage Structure Sequence

- 1. Install silt fencing on the north end to prevent drainage in to the "potential wetlands area".
- 2. Strip topsoil starting with:
 - a. Soil units Be, PCE2, MW (the RY formation has no recoverable soil)
 - b. Strip soil unit CcE2 and place on top of soil units Be, PCE2 and MW.
- 3. Construct topsoil retention berm and retention pond
- 4. Construct temporary drainage ditch on southeast end.
- 5. Construct excavation stockpile retention berm and pond.
- 6. Construct sediment pond in northcast corner.

If you any questions or concerns please feel free to contact me at (435) 286-3512.


Sincerely,

Seth McCourt

1) Court

EMERY 4th East Porte

Revised soils Map == NHENHUIS May 31



KLB Fe PCFL RY CEE2

Be Begay Mw Montwell

